Ref No.:	P-247/WO/POP-Gypsum-Putty/M&L//T1/R0	Date: 008-03-2021
Project Name:	RVG Hostel	
Subject:	BOQ & Rates for POP-Gypsum-Putty Works	

	ANNEXURE "	'A"				
ir. No.	DESCRIPTION OF ITEMS	APPROVED MAKES OF MATERIALS	UNIT	QTY	UNIT RATE	AMOUNT
Α	POP WORKS:					
A.1	CEILING: Providing & Applying POP on UN-PLASTERED CEILING in line level finish, as per site incharge instructions:					
	Room Type -1:			+	1	
A.1.'	1 upto 12mm thickness : For Room area ceiling	Supreme / Diamond / Lucky / Hitech-SuperFine	Sqft	14,540	1	₹0
	Room Type -2:		• 1		ł	
A.1.;	2 upto 12mm thickness : For Room area ceiling	Supreme / Diamond / Lucky / Hitech-SuperFine	Sqft	1,649	1	₹0
	Room Type -3:		- ,		1	
A.1.(3 upto 12mm thickness : For Room area ceiling	Supreme / Diamond / Lucky / Hitech-SuperFine	Sqft	2,939	l – – –	₹0
	Room Type -4:		· · · ·	2,000	l	
A 1 4	4 upto 12mm thickness : For Room area ceiling	Supreme / Diamond / Lucky / Hitech-SuperFine	Sqft	619	l	₹0
	Common areas:	Supreme / Diamond / Edoxy / Inteen Caper	- Oyit	0.0	l	
Δ1/	5 upto 12mm thickness : For Lift-lobby area ceiling	Supreme / Diamond / Lucky / Hitech-SuperFine	Sqft	6,150	l	₹0
	6 upto 12mm thickness : For Staircase area ceiling	Supreme / Diamond / Lucky / Hitech-SuperFine	Sqft	2,523	┟─────	₹0
A.1.0	<u>WALLS (DHADA finish)</u> : Providing & Applying POP on <i>CEMENT-PLASTERED WALLS</i> in line level finish, as per site incharge instructions:		ο γιι	2,020		
	Room Type -1 to Room Type - 4:					
A.2.1	1 upto 12mm thickness : For Room area walls	Supreme / Diamond / Lucky / Hitech-SuperFine	Sqft	51,393		₹0
	Common areas:			1		
A.2.2	2 upto 12mm thickness : For Lift-Lobby area walls	Supreme / Diamond / Lucky / Hitech-SuperFine	Sqft	20,025		₹0
A.2.3	3 upto 12mm thickness : For Staircase area walls	Supreme / Diamond / Lucky / Hitech-SuperFine	Sqft	1,928		₹ (
			Total of "PO	P WORKS" (A):	₹0	
В	GYPSUM PLASTER WORKS:					
	Total of "GYPSUM PLASTER WORKS" (B):					
С	PUTTY WORKS:					
			Total of "PUTT	Y WORKS" (C):	₹0	
D	FALSE CEILING WORKS:					
D.1	Gypsum False-Ceiling with Gypsum board & G.I. Patra framing with all necessary materials, tools, equipment etc complete.,	All fittings & board: Gyproc/Rockmelt, GI-Patti	Sqft	6,150		₹ (
	for All Floor Lift-lobby	thickness: 120 gsm, Board thickness: 12mm	Sqit	0,100		
D.2	Gypsum False-Ceiling-Facia-Patti (25mm to 230mm wide) with Gypsum board with all necessary materials, tools, equipment etc complete., for Sample-flat, Gr. Floor Lift-lobby, Gym-area & Gym-toilets	All fittings & board: Gyproc/Rockmelt, GI-Patti thickness: 120 gsm, Board thickness: 12mm	RFT	1,920	1	₹(
			FALSE CEILIN	G WORKS" (D):	₹0	
E	MISC. ITEMS					
	Providing and making 6mm Groove in Gypsum/POP with smooth finish complete (All sides of Doors & Window frames and		Caft			
E.1	Skirting), as per site incharge instructions.		Sqft	QRO	 	
	Repair of POP/Gypsum due to Jari/Wall-cutting reqd for MEP works: Providing & doing POP/Gypsum repair jobs required for finishing of Jari/Plaster-cutting done for MEP re-working. This Plaster-cutting is considered as maximum 12" wide					
	at any point.	1		QRO		
	at any point. 2 POP/Gypsum contractor MUST ensure that civil-contractor has laid PVC Chicken-Mesh on all type of jari/wall-cutting done on walls/ceiling for MEP works, before re-plastering such Jari/wall-cutting works. If civil-contractor has not put PVC Chicken- mesh, POP/Gypsum contractor MUST NOT repair the wall/ceiling otherwise later if any crack appears due to non-existance of such Mesh. POP/Gypsum contractor has to repair-such cracks at his own cost.		Rft			
	2 POP/Gypsum contractor MUST ensure that civil-contractor has laid PVC Chicken-Mesh on all type of jari/wall-cutting done on walls/ceiling for MEP works, before re-plastering such Jari/wall-cutting works. If civil-contractor has not put PVC Chicken-mesh, POP/Gypsum contractor MUST NOT repair the wall/ceiling otherwise later if any crack appears due to non-existance of such POP/Gypsum contractor has to rangic such cracks at his own cost.					₹
	2 POP/Gypsum contractor MUST ensure that civil-contractor has laid PVC Chicken-Mesh on all type of jari/wall-cutting done on walls/ceiling for MEP works, before re-plastering such Jari/wall-cutting works. If civil-contractor has not put PVC Chicken- mesh, POP/Gypsum contractor MUST NOT repair the wall/ceiling otherwise later if any crack appears due to non-existance of		Sqft	34,569		₹(
	2 POP/Gypsum contractor MUST ensure that civil-contractor has laid PVC Chicken-Mesh on all type of jari/wall-cutting done on walls/ceiling for MEP works, before re-plastering such Jari/wall-cutting works. If civil-contractor has not put PVC Chicken-mesh, POP/Gypsum contractor MUST NOT repair the wall/ceiling otherwise later if any crack appears due to non-existance of such POP/Gypsum contractor has to rangic such cracks at his own cost.		Sqft		₹0	₹ C author:-

Negotiated / Not-negotiated

Note (for contractor, while quoting his price):-

1) Taxes will be extra as actual.

2) Material loading & Unloading is in contractor's scope, at his own cost, for all materials being supplied/brought by client/contractor for incorporating in his scope of works (including mathadi charges, if applicable).

3) Material lifting and shifting from ground to required place is in contractor's scope, at his own cost, for all materials being supplied/brought by client/contractor for incorporating in his scope of works.

4) All required scaffolding and supporting, to complete his scope of works, is in contractor's scope at his own cost.

5) All measurements will be considered of exactly executed sizes. It will not be rounded to nearest 3"/6"/9"/12".

6) Marble/Tile protection POP material to be brought by contractor at his own cost, if in his contract. It is to be removed by contractor at his own cost, as per Nexus site-engineer's instruction.

7) Contractor to bring all his debris at ground-floor, at the prescribed location, and stack it as instructed by Nexus site-engineer. Client to throw away such debris from site, at his own cost.

8) Contractor is expected to do POP/Gypsum above skirting, after skirting is fixed, without charging any extra amount to client for the delay in skirting fixing.

9) Contractor is expected to do POP/Gypsum near window/door frames, after frames are fixed, without charging any extra amount to client for the delay in frame fixing.

10) Paying PF and ESIC is in scope of contractor, at his own cost.